



INTERMOUNTAIN UNIT 1 & 2

HEATER 8 DUTY

(A) OEM @ 5% Overpressure 481 HB 784



(B) UNIT 1 BMCR Test 1998 (ALSTOM Calculation)



(C) UNIT 2 BMCR Test 1998 (ALSTOM Calculation)

